HISTORIC AMERICAN BUILDINGS SURVEY

INDEX TO PHOTOCRAPHS

Fort Vancouver, Artillery Stables (Old Mule Barn)
Fort Vancouver
Vancouver
Clark County
Washington

HABS No. WA-41C

Bergman Photographic Services, Photographer July 1985	
WA-41C-1	NORTH FRONT
WA-41C-2	WEST SIDE (STORACE YARD IN FORECROUND)
WA-41C-3	WEST SIDE, SOUTH TO THE RICHT
WA-41C-4	SOUTH END
WA-41C-5	EAST SIDE, SOUTH TO THE LEFT
WA-41C-6	EAST SIDE, NORTH TO THE RICHT
WA-41C-7	SOUTH END LOOKING NORTHEAST. BRICK WALL CONNECTS OLD MULE BARN TO EXISTING LABORATORY
WA-41C-8	DOORWAY DETAIL ON EAST SIDE
WA-41C-9	DETAIL OF WEST DOORWAY
WA-41C-10	DETAIL OF LARGE WINDOW. SILL AND BRICK CONDITION ARE TYPICAL
WA-41C-11	DETAIL OF SMALL WINDOW (TYPICAL)
WA-41C-12	TYPICAL DETAIL OF LOUVERS AND WINDOWS IN MONITOR. NOTE USE OF SLATE SHINCLES TO FACE MONITOR WALL
WA-41C-13	CURVED RAFTER ENDS ON LOWER ROOF
WA-41C-14	CURVED RAFTER ENDS ON MONITOR ROOF
WA-41C-15	INTERIOR LOOKING SOUTH
WA-41C-16	INTERIOR LOOKING NORTH, NOTE ALTERNATE 8" x 8" POSTS HAVE BEEN CUT OFF
WA-41C-17	INTERIOR FRAMINC, FACINC SOUTH WALL ABOVE DOORWAY
WA-41C-18	TYPICAL NORTH HALLWAY. NOTE ORICINAL BRICK FLOORING. ROOM B IN BACKCROUND.

- WA-41C-19 ROOM A, SOUTH HALF
- WA-41C-20 , ROOM B
- WA-41C-21 STORACE ROOM. CONCRETE FLOOR WAS POURED ON TOP OF EXISTING BRICK FLOOR
- WA-41C-22 ORIGINAL BARN DOORS AND BRICK FLOORING
- WA-41C-23 DETAIL OF ORIGINAL BRICK FLOORING NEAR NORTH BARN DOORS
- WA-41C-24 GUTTER AND INLET BASIN
- WA-41C-25 SOUTHWEST CORNER OF LOFT. STAIRWAY ENTERS CENTER BACKGROUND
- WA-41C-26 EAST WALL OF LOFT. WEST WALL IS IDENTICAL
- WA-41C-27 NORTH WALL OF LOFT
- WA-41C-28 MONITOR, PEAK FRAMING DETAIL
- WA-41C-29 BEARING POST, MONITOR WINDOWS AND LOUVER IN BACKGROUND
- WA-41C-30 MONITOR: INTERIOR LOUVER DETAIL ONE-HALF OPEN
- WA-41C-31 TYPICAL WINDOW FROM INTERIOR
- WA-41C-32 INTERIOR VIEW OF EAST DOORWAY